## WATER WELL REPORT STATE OF WASHINGTON

Permit No. . . .

(1) OWNER: Name Lehman , James	Address 4134 6 OFER 415 Bol Clins	tn 88234
(2) LOCATION OF WELL: County Lilony	_ 56 4 NW4 Se 26 T 24	N., R. 3. W.M.
Bearing and distance from section or subdivision corner	1 893 N of SW com. Sec 7	24
(3) PROPOSED USE: Domestic Industrial Municipal	(10) WELL LOG:	
Irrigation □ Test Well □ Other □	Formation: Describe by color, character, size of material an show thickness of aquifers and the kind and nature of the	ed structure, and
(4) TVDF OF WORK. Owner's number of well	stratum penetrated, with at least one entry for each chan	ge of formation.
(4) III E OF WORK. (if more than one)	MATERIAL F	ROM TO
New well  Method: Dug  Bored  Deepened  Cable  Driven	Top seil	2 4
Reconditioned  Rotary Jetted	Hard Pan	100
(5) DIMENSIONS		ou 120
(5) DIMENSIONS:  Drilled 150 ft. Depth of completed well ft.		144
Drifted a gradual transfer of completed with	Hara Pan	44 111
(6) CONSTRUCTION DETAILS:		
Casing installed: Dlam. from		
Threaded 🗋		
Welded Diam. from ft. to ft.		
Perforations: yes □ No ■		
Type of perforator used		
SIZE of perforations in. by in.		<u> </u>
perforations from ft. to ft.		
perforations from ft. to ft. perforations from ft. to ft.		
perforations from		
Screens: Yes No 🗆		
Manufacturer's Name COOK		
Type 1.5 wild Model No. Diam. 6 Slot size 6 from 161 ft. to 1.55 ft.		
Diam. Slot size from ft. to ft.		
		<del></del>
Gravel packed: Yes   No Size of gravel:		
Gravel placed from ft. to ft.		—— <del> </del>
Surface seal: Yes No D To what depth? 30 nt.		
Material used in seal Bea bone 1		
Did any strata contain unusable water? Yes 🗆 No 🔮		
Type of water? Depth of strata		
		<del> </del>
(7) PUMP: Manufacturer's Name.	1.	
Туре: Н.Р		
(8) WATER LEVELS: Land-surface elevation above mean sea level		
Static level 101		
Artesian pressureibs. per square inch Date		
Artesian water is controlled by (Cap, valve, etc.)		
		<u> </u>
(9) WELL TESTS: Drawdown is amount water level is lowered below static level	Work started 2 3 Completed 2	198.1
Was a pump test made? Yes No 🗆 If yes, by whom?	WELL DRILLER'S STATEMENT:	
Yield: 30 gal./min. with 48 ft. drawdown after 4 hrs.	1	
0 0	This well was drilled under my jurisdiction an true to the best of my knowledge and belief.	d this report is
Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)	NAME POLL BOSH MAY	
Time Water Level   Time Water Level   Time Water Level	NAME (Person, firm, or corporation) (Ty	pe or print)
	Ac Box EC Freeland	
	Address A.C. Bas S.S. Freeland	
	1 1 - 4 < 11	, 
Date of test has	[Signed (Well Driller)	<b>T</b>
Bailer test gal./min. with ft. drawdown after hrs.  Artesian flow g.p.m. Date		<b>~</b> !
Temperature of water Was a chemical analysis made? Yes No	License No. 243 Date 2	19. <b>K</b> .Z.
Total Control of the		